Oil Field Environmental Incident Summary

Responsible Party: SLAWSON EXPLORATION COMPANY, INC. **Well Operator:** SLAWSON EXPLORATION COMPANY, INC.

Well Name: NIGHTCRAWLER 2-17H

Field Name: VAN HOOK Well File #: 18954

Date Incident:6/29/2015Time Incident:10:15Facility ID Number:County:MOUNTRAILTwp: 152Rng: 91Sec: 17Qtr:

Location Description:

Submitted By: Raymond Gorka Received By:

Contact Person: Ray Gorka

1675 BROADWAY STE 1600

DENVER, CO 80202

General Land Use: Cultivated Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.5 MileDistance Nearest Water Well:0.5 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	10	Gallons	10	Gallons	10	gallons	
Brine	200	Gallons	198	Gallons	200	gallons	

Other

Description of Other Released Contaminant:

.

Inspected: Written Report Received: 4/11/2016 Clean Up Concluded: 6/30/2015

Risk Evaluation:

none....

Areal Extent:

.....

Potential Environmental Impacts:

none.....

Action Taken or Planned:

Better training of personnel..

Wastes Disposal Location: licensed disposal facility, and SWD.

Agencies Involved:

Updates

Date: 7/1/2015 Status: Correspondence Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spoke with a NDIC field inspector, via phone at 10:35 a.m. He let me know that the facility had a steel secondary containment system for the release and no impacts were noted beyond the containment system. No further follow-up needed at this time. NDIC retains oversight.

Date: 7/1/2015 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained within diking, according to the report. NDIC retains oversight.